# Fire Department For the City of Mt. Juliet Mt. Juliet, Tennessee

## 37.8M fire extinguishers made over 44 years recalled; 1 death reported

According to the CPSC, it involves two styles of Kidde fire extinguishers: Plastic handle fire extinguishers and push button fire extinguishers. They may fail to discharge and the nozzle may detach.

The 134 models were manufactured between Jan. 1, 1973 and Aug. 15, 2017, and includes models that have been previously recalled in March 2009 and February 2015.

They were sold in red, white and silver and are either ABC- or BC-rated.

According to the CPSC, there has been one death reported due to the recall. In 2014 emergency responders could not get the fire extinguishers to work during a car fire. There have also been 391 reports of failed or limited activation nozzle detachment, 16 injuries and 91 reports of property damage.

They were sold at Menards, Montgomery Ward, Sears, The Home Depot, Walmart and other department, home and hardware stores across the country, and at Amazon.com.

Consumers should contact Kidde to request a free replacement fire extinguisher.

FAQ

Plastic Handle/Bush-Button Pindicator Fire Extinguisher Recall

Q: Why is Kidde recalling products?

A: We are recalling certain Kidde fire extinguishers due to a potential safety issue. As consumer safety is our priority, we are working with the U.S. Consumer Product Safety Commission (CPSC) and other relevant authorities to notify customers with

instructions for returning the affected models and how to replace them with different, unaffected models.

Q: How can I find out if my fire extinguisher is included in the recall?

A: Please contact us at (855) 271-0773 between 8:30 a.m. and 5 p.m. EST Monday-Friday (excluding holidays), or between 9 a.m. and 3 p.m. during the weekend to determine whether your extinguishers are affected. Alternatively, detailed information about which products are included is available below.

Q: How do I get a replacement?

A: Please contact us at (855) 271-0773 between 8:30 a.m. and 5 p.m. EST Monday-Friday (excluding holidays), or between 9 a.m. and 3 p.m. during the weekend to determine whether your extinguishers are affected. If it is determined that you do have an affected fire extinguisher, a replacement will be shipped within approximately 10 to 15 business days from this call. Please keep your affected unit until the replacement arrives. Please note, if your model is used with a personal watercraft, Kidde does not currently have an exact replacement for it, but is prepared to offer you a replacement extinguisher which is both US Coast Guard rated, and is similar in size. While it may not fit in the same location as the extinguisher that you currently have, there may be another space on your watercraft in which you can store this extinguisher.

Q: Do I need a receipt? How do I demonstrate my eligibility for a replacement?

A: No proof of purchase is required. Please supply the model number, year of manufacture, the unit's date code and serial number. Additional information may

also be requested. You can find the model number and serial number on the unit's label.

Q: If I have an affected unit, what should I do with it?

A: Please retain your existing extinguisher(s) until your replacement(s) has been received. Upon receipt of your new fire extinguisher(s) you will find instructions for returning the recalled unit(s).

#### View the list of affected product codes below or by <u>clicking here</u>

#### Plastic-handle models produced between January 1, 1973 and October 25, 2015

2A40BC	Gillette TPS-1 1A10BC	Sams SM 340
6 RAP	Home 10BC	Sanford 1A10BC
6 TAP	Home 1A10BC	Sanford 2A40BC
Ademco 720 1A10BC	Home 2A40BC	Sanford TPS-1
		1A10BC
Ademco 722 2A40BC	Home H-10 10BC	Sanford TPS-1
		2A40BC
ADT 3A40BC	Home H-110 1A10BC	Sears 2RPS 5BC
All Purpose 2A40BC	Home H-240 2A-40BC	Sears 58033 10BC
Bicentenial RPS-2 10BCHoneywell 1A10BC		Sears 58043 1A10BC
Bicentenial TPS-2 1A-	Honeywell TPS-1 1A10BC	Sears 5805 2A40BC
10BC		
Costco 340	J.L. 2A40BC	Sears 958034
FA 340HD	J.L. TPS-1 2A40BC	Sears 958044
FA240HD	Kadet 2RPS-1 5BC	Sears 958054
FC 340Z	Kidde 10BC	Sears 958075
FC Super	Kidde 1A10BC	Sears RPS-1 10BC
FC210R-C8S	Kidde 2A40BC	Sears TPS-1 1A10BC

Fire Away 10BC	Kidde 40BC	Sears TPS-1 2A40BC
Spanish		
Fire Away 1A10BC	Kidde RPS-1 10BC	Traveler 10BC
Spanish		
Fire Away 2A40BC	Kidde RPS-1 40BC	Traveler 1A10BC
Spanish		
Fireaway 10 (F-10)	Kidde TPS-1 1A10BC	Traveler 2A40BC
Fireaway 10BC	Kidde TPS-1 2A40BC	Traveler T-10 10BC
Fireaway 110 (F-110)	KX 2-1/2 TCZ	Traveler T-110
	,	1A10BC
Fireaway 1A10BC	Mariner 10BC	Traveler T-240
,		2A40BC
Fireaway 240 (F-240)	Mariner 1A10BC	Volunteer 1A10BC
Fireaway 2A40BC	Mariner 2A40BC	Volunteer TPS-V
ý		1A10BC
Force 9 2A40BC	Mariner M-10 10BC	XL 2.5 TCZ
FS 340Z	Mariner M-110 1A10BC	XL 2.5 TCZ-3
Fuller 420 1A10BC	Mariner M-240 2A40BC	XL 2.5 TCZ-4
Fuller Brush 420	Master Protection 2A40BC	XL 2.75 RZ
1A10BC		
FX210	Montgomery Ward 10BC	XL 2.75 RZ-3
FX210R	Montgomery Ward 1A-10B0	
FX210W	Montgomery Ward 8627	XL 340HD
11121011	1A10BC	112 0 10112
FX340GW	Montgomery Ward	XL 4 TXZ
	8637 10BC	
FX340GW-2	Quell 10BC	XL 5 PK
FX340H	Quell 1A10BC	XL 5 TCZ
FX340SC	Quell RPS-1 10BC	XL 5 TCZ-1
FX340SC-2	Quell TPS-1 1A10BC	XL5 MR
Gillette 1A10BC	Quell ZRPS 5BC	XL 6 RZ
	Quality and and	

### Plastic-handle models with date codes between January 2, 2012 and August 15, 2017 $\,$

AUTO FX5 II-1	FC5	M10G
FA10G	FS10	M10GM

FA10T	FS110	M110G
FA110G	FS5	M110GM
FA5-1	FX10K	M5G
FA5G	FX5 II	M5GM
FC10	H110G	RESSP
FC110	H5G	

**Push-button Pindicator fire extinguishers:** The recall involves eight models of Kidde Pindicator fire extinguishers manufactured between August 11, 1995 and September 22, 2017. The no-gauge push-button extinguishers were sold in red and white, and with a red or black nozzle. These models were sold primarily for kitchen and personal watercraft applications.

#### Push Button Pindicator Models manufactured between August 11, 1995 and September 22, 2017

KK2	M5PM
100D	AUTO 5FX
210D	AUTO 5FX-1
M5P	FF 210D-1